



2x
18654
Black



1x
6541
Black



20x
2780
Black



4x
3023
Black



1x
75535
Black




1x
32000
Black



4x
3004
Black



14x
3700
Black




2x
3003
Black



2x
3622
Black



2x
6232
Black



8x
4730
Black



2x
3002
Black



4x
3701
Black



8x
3020
Black



1x
3894
Black



1x
3795
Black



1x
32524
Black



1x
3702
Black

3702: Technic Brick 1 x 8




1x
3007
Black

3007: Brick 2 x 8



4x
4477
Black

3036: Plate 6 x 8




1x
32532
Black

32532: Technic 6 x 8




6x
3036
Black



3832: Plate 2 x 10

4x
3832
Black



3033: Plate 6 x 10

4x
3033
Black




41539: Plate 8 x 8

2x
41539
Black




3708: Axle 12

1x
3708
Black



4x
3895
Black

3895: Technic Brick 1 x 12




2x
3027
Black

3027: Plate 6 x 16



1x
32018
Black

32018: Technic Brick 1 x 14




2x
71710
Dark Bluish Gray


71710: Technic, Liftarm,
Modified Perpendicular Holes
Thick 1 x 15




5x
3713
Light Bluish Gray




2x
32198
Light Bluish Gray



1x
87407
Light Bluish Gray



1x
2958
Light Bluish Gray



1x
3702
Light Bluish Gray

3702: Technic Brick 1 x 8




2x
3895
Light Bluish Gray


3895: Technic Brick 1 x 12




3x
4073
White




2x
3023
White




2x
3004
White




2x
3700
White



4x
2357
White




1x
53787
White




6x
6628a
Red




2x
14149
Red




1x
3701
Red




1x
32524
Red



1x
3020
Red




1x
32316
Red



3708: Axle 12

2x
3708
Red



3895: Technic Brick 1 x 12


3x
3895
Red




1x
6222
Brown



1x
3024
Orange




1x
32316
Orange




2x
60485
Yellow

60485: Axle 9



1x
32316
Lime




2x
3795
Orange

3795: Plate 2 x 6




8x
4265c
Yellow




3x
3006
Yellow

3006: Brick 2 x 10



2x
3795
Lime


3795: Plate 2 x 6




7x
3001
Yellow



1x
4073
Bright Light Yellow



1x
3024
Lime




3028: Plate 6 x 12


2x
3028
Bright Green




3x
6558
Blue




1x
3622
Blue



1x
3701
Blue




1x
3020
Blue



1x
32316
Blue




1x
32524
Blue



1x
3895
Blue


3895: Technic Brick 1 x 12







1x
32018
Blue

32018: Technic Brick 1 x 14



1




2




3




4








5




6




7




8






9




10




3795: Plate 2 x 6




11








12




13




14







15




16






17





18





19





20




21





22





23




24




25






26




27




28




29




3036: Plate 6 x 8





30




41539: Plate 8 x 8





31




32






33




34




35




36




37




3832: Plate 2 x 10 3895: Technic Brick 1 x 12




38




4477: Plate 1 x 10





39




4477: Plate 1 x 10 3895: Technic Brick 1 x 12



40




41



3832: Plate 2 x 10





42




4477: Plate 1 x 10






43





44





45





46





47





48




49






50





51





52





53




54




55




56








57




58




59









60




61




62




63




64



71710: Technic,
Liftarm, Modified
Perpendicular
Holes Thick 1 x 15





65





1:1



66






67





68





69





70



71



72



73

